



Firmware Change Log

June 8, 2009

OCZ Engineering

Version 1.3

Release Date: June 03, 2009

Bug fixes

- Host program lost drives if NAND BIST is run on multiple drives.
- Read Fail handling
- ATA Security Command didn't work as expected.
- Race condition occurred during soft reset handler
- ATA Security Command didn't work in AHCI mode.
- If read fail occurs during reading stamp information, firmware corrupted block 0.
- Power off recovery had bug in certain circumstances
- If host sends invalid SMART subcommands, Abort was not sent to host.
- SMART attribute data was not initialized properly for certain fields.
- Improper handling of ATA command when sent with 0 sector count

Feature Addition

- Remaining life expectancy calculation is implemented.

Version 1.10

Release Date : April 7, 2009

Feature Addition

- Proprietary TRIM support is added
- Apple Mac Pro sleep/wake up support added

Version 1275

Release Date: March 2009

Bug Fixes

- Maximum LBA number is modified according to the JEDEC standard

Feature Addition

- Various changes for performance improvement

Version 1199

Release Date: Feb. 2009

Feature Addition:

- SMART basic features can be performed without error log
- ATA power management commands (IDLE, STANDBY, SLEEP) are enabled for compatibility
- Enabled PIO mode data transfer

